

From: (b) (6) NDW Region Security Officer

To: LCDR (b) (6)

SUBJECT: REPSONSE TO INQUIRIES INTO FINAL DENIAL BARRIER STATUS AT WNY

1. Mr. (b) (6) per our conversation, the following is provided:

a. Current Guidance on Barrier Repair

(b) (7)(E), (b) (7)(F)



d. All installations within NDW have been made aware of the proper reporting requirements and history indicates that they have reported deficiencies correctly. The disconnect at NSAW could be attributable to leadership turnover within the NSAW organization over the past year.

(1) NDW N3AT will engage with the current leadership to ensure that they are made aware of the reporting requirements and that they have the support required to meet those requirements.

(b) (6)

THE INSTALLATION WILL CONDUCT AN OPTEST OF THE BARRIERS ON 03 OCT AND PROVIDE RESULTS TO NDW N3AT. BASED ON THAT TEST, THE NOTIFICATION PROCESS TO USEF NO42 AND MAKE PROPER ENTRIES INTO CAI WITH EMAIL TRAFFIC. (b) (6)